July 6, 2015   Document # SB-2326

Service Bulletin

Mini-Recorder Firmware v0.34.22_RC1 (Beta)

Applicability: This beta release applies only to Titan High Speed Mini-Recorders that include an Internal Digital Pod.

NOTE: This beta release is not for global distribution

Description: The Titan High Speed v0.34.22_RC1 firmware improves the throughput of the Internal Digital Pod, preventing data dropouts.

Update: The Titan High Speed Firmware requires the use of the Titan Programmer. The Programmer is available as a download from the Mars Labs Knowledge Base; it is also available as an update utility that is built into in TCS (select it in the TCS 'Device/Advanced' menu).

Help: For additional information or assistance, please contact:

Mars Labs
Phone: 301-470-3278
Email: support@marslabs.com
www.marslabs.com