



Mars Labs
29 C Street
Laurel, MD 20707

December, 2014

Document # SB-2297

Service Bulletin

Titan Mini-Recorder Firmware v0.34.16

Applicability: This release applies to Titan High Speed Mini-Recorders and High Speed Pods

Description: The Titan High Speed v0.34.16 firmware offers improved noise performance on channels 1 and 15, as well as clock output support for USB-based CPUs. This release is recommended for all Titan High Speed Mini-Recorders and Pods.

Update: This firmware is available on the Mars Labs Knowledge Base:

<http://wiki.marslabs.com/doku.php>

Note that you will need a login name and password – please contact Mars Labs to obtain login credentials if you have not already been supplied the information.

Download both the High Speed Firmware and the standalone Titan Programmer. You will need both files in order to update your Titan device.

Note: You can also update the firmware using the built-in firmware update utility in TCS, located in the 'Device/Advanced' menu.

Drag-and-drop the files to your desktop or other folder on your PC.

Titan Firmware Updates file: **High Speed Firmware v0.34.16**

Standalone Titan Programmer file: **Titan Firmware Programmer**

Documentation on updating the firmware for Titan devices is contained in a PDF document provided with the Titan Programmer.

Help: For additional information or assistance, please contact:

Mars Labs
Phone: 301-470-3278
Email: support@marslabs.com
www.marslabs.com